

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY
2951 E. COLORADO ST., PASADENA, CALIF.

No. 11025

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080008-5

RECEIVED FROM

DATE REC'D 3-24-57

P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO
QUANTITY
RECEIVED

CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPR. # NUMBER	BUY OUT CODE NO.	O ACCT. OR W.O. NO.	R S.O. NO.	REMARKS
	322 000000	12140	0	0	00	00				
CHARGE TO QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION						QUANTITY	ACCEPTED	REJECTED	REMARKS
12	731258-1 "D" ROCKER BRAKE						12			
	SHIPPER 85852									
	TO SUPPLY&EQUIP 128151									

REJECTS RETURNED
ON SHIP. MEMO NO.RECEIVED
BY
HMC-1069INSPECTED
BY

Date 1/25/57

RECEIVED FROM

RECEIVING INSPECTION REPORT
HYCON MFG. COMPANY
2951 E. COLORADO ST., PASADENA, CALIF.

No. 11026

CHARGE TO
QUANTITY
RECEIVEDDATE REC'D
P.O. NO.

3-23-57

CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPR. # NUMBER	BUY OUT CODE NO.	O ACCT. OR W.O. NO.	R S.O. NO.	REMARKS
	322 000000	12140	0	0	00	00				
CHARGE TO QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION						QUANTITY	ACCEPTED	REJECTED	REMARKS
12	731258-2 "D" ROCKER BRAKE						12			
	SHIPPER 85852									
	TO SUPPLY&EQUIP 128152									

REJECTS RETURNED

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080008-5

RECEIVED
BY
HMC-1069INSPECTED
BY

Date 1/25/57